

Document Title	Number	Rev	Date	Type
E3844038-4 1 st Stage Stator, GTCP331-200 Repair Limits	M-100	A	2/12/16	ILR
E3611904-1 Turbine Shroud	T-301	B	2/08/16	ILR
E3840004-5 1 st Stage Turbine Blade and E3840008-2 2 nd Stage Turbine Blade	T-401	B	2/08/16	ILR
E3826099 IG V, EN3826099 IG V, Nickel	T-402	B	2/08/16	ILR
Second Stage Turbine Blade Radiographic Inspection Information	T-404	B	2/08/16	ILR
Honeywell GTCP 36, 331, 85 series, and 700 series APU's	T-501	F	2/08/16	ILR
3840223-4E, E3840282-3 1 st Stage Turbine Blades	T-601	C	2/08/16	ILR
E3604912-6 Blade, HP Turbine Rotor Inspection Information, Service Bulletin	T-650	A	2/12/16	SB
Service Information Letter: High Pressure Turbine Blades-Recent Issues E3604912-6	T-651	A	2/10/16	SB