



TECHNICAL MANUAL
Table of Contents

Document Title	Number	Rev	Date	Type
EXTEX Replacement Parts for Certain Pratt & Whitney Canada PT6A and PT6T Engine Models	T-800	C	2/12/16	ILR
3013102E/E3013102, 3030102E/E3030102 Power Turbine Blade Inspection, Repair Limits and Overhaul Criteria	T-801	D	2/12/16	ILR
E3123131-02, E3123071-01 Blade, CT	T-802	D	2/12/16	ILR
PT6A Oil System Monitoring for Reduction Gear Bearings Set No. E3035020 (P/N E3101985-03), Set No. E3035029 (P/N E3101985-05), Set No. E3035030 (P/N E3101985-02), Set No. E3035031 (P/N E3101985-01)	T-803	B	2/12/16	SB
PT6A Increased Monitoring of Chip Detector, E3024765	T-804	C	2/12/16	Alert SB
PT6A Increased Monitoring of Engine Chip Detectors, E3028456, E3037304, E3101455-02, E3101525-02	T-807	A	2/12/16	Alert SB
PT6A Instructions for Removal of Sun Gear P/N's E3028456, E3037304 and Planet Gear P/N's E3101455-02, E3101525-02	T-808	A	2/12/16	Alert SB
E3045741-01 Blade, Turbine Compressor	T-809	B	7/12/17	ILR
To Be Determined	T-810		TBD	ILR
Compressor Turbine Blade Inspection (E3045741-01)	T-811	B	2/12/16	SB
Service Bulletin (AMOC to AD 2014-17-08R1) (E3045741-01)	T-812	A	7/17/18	SB
Service Information Letter (Compressor Turbine Blade Coating - E3045741-01)	T-813	IR	3/14/17	SIL
PT6A Instructions for Removal of Tie Rod P/N's E3019371	T-814	IR	8/10/18	Alert SB
Service Bulletin (E3045741-01)	T-815	IR	8/21/19	SB
Service Bulletin (E3045741-01)	T-816	IR	8/21/19	SB
Service Bulletin (E3045741-01)	T-817	IR	8/21/19	SB
Service Bulletin (E3121111-01)	T-818	IR	5/18/26	SB